


Τ









MMOPA NATIONAL CONVENTION 2023 - COLORADO SPRINGS




3

1. Service Letters & Bulletins

- Piper SL1286D Nose Gear Inspection
- Piper SL 1315 Elevator Trim Tab Rods

MOPA NATIONAL CONVENTION 2023 – COLORADO SPRINGS





PA 46 Nose Strut

MMOPA NATIONAL CONVENTION 2023 - COLORADO SPRINGS

MEDIA NATIONAL CONVENTION 2023 - COLORADO SPRINGS

PRESENTATIONAL CONVENTION 2023 - COLORADO SPRINGS

PRESENTATION 2023 - COLORADO SPRINGS

3. AD 2023 -09-09 Turbo Tailpipe Clamps









7

3. AD 2023 -09-09 Turbo Tailpipe Clamps


Continental Models Only:


Replace spot-welded clamps every 500 hours.

IF clamps are not available, in lieu of replacement, inspect turbo tail pipe clamps every 6 months or 100 hours which ever is first for up to 2 years. [Effective date July 17, 2023]

IMOPA NATIONAL CONVENTION 2023 – COLORADO SPRINGS







3. AD 2023 -09-09 Turbo Tailpipe Clamps

AD 2010-13-07:

On Lycomings where the spot-welded clamps have been replaced with riveted style clamps, no action is required.

Piper SB884 Lock Wire V-Band Clamps:

Prevents separation of clamp if the T-Bolt breaks.

11

MMOPA NATIONAL CONVENTION 2023 – COLORADO SPRINGS



11

4. Cylinder Woes MMOPA NATIONAL CONVENTION 2023 - COLORADO SPRINGS **MEANT BEVOLEN INC.







